



## Instructions for use

- **Surface treatment of the substrate**

Before application, the substrate must be perfectly dry, clean and free from any traces of grease, oils and any removable or foreign substances.

- **Method of application**

**For satin finish**

Apply a coat of superglaze 1:1 with water onto the perfectly dried coating.

**For gloss finish**

Apply a coat of superglaze without water onto the perfectly dried coating.

**N.B** on particularly absorbent coating it may be necessary to apply a second coat of superglaze, allowing the underlying coat to dry well before proceeding with the second coat.

It is possible to denote a less glossy optical effect when Superglaze is applied to rough textured coating.

- **Storage**

The product must be stored in original sealed drums, at temperatures not inferior to 0°C, protected from direct sunshine and strong heat.

- **Warnings and suggestions**

It is advisable to mix the product well before use. The ambient temperature for application is recommended to be between + 5°C and + 40°C.

The application should be carried out sheltered from direct sunshine, strong winds and rain. Use only fresh, clean water for eventual thinning.

Wash working tools and eventual spots of product from surrounding parts with water before the product is dried.

The technical data and methods reported in this technical data sheet are subject to variations at any time according to the latest development in the production technology. The technical service of Trust is at the user disposal for the supply of integrative information to the herein reported.